

FIG. 1




FIG. 2




FIG. 3




FIG. 4A

5/6




FIG. 4B

FIG. 5A

$+\Delta_1$	$-\Delta_1$
$+\Delta_2$	$-\Delta_2$
$\vdots$	$\vdots$
$+\Delta_j$	$-\Delta_j$

$i = 16$																
$j = 4$	1	0	0	1	1	0	0	1	0	1	1	0	0	1	1	0
	1	0	0	1	0	1	1	0	0	1	1	0	1	0	0	1
	1	0	0	1	0	1	1	0	1	0	0	1	0	1	1	0
	1	0	1	0	0	1	0	1	1	0	1	0	0	1	0	1

FIG. 5B

$i = 16$															
PER <sub>1</sub> PER <sub>2</sub> PER <sub>16</sub>															

FIG. 5C